



▶ TEST REPORT No KA-167-4-019

13.05.2014

Product: Remote system for oil pollution detection
Name and address of the applicant: Laser Diagnostic Instruments AS, Valukoja street 11415
Tallinn, Estonia
Land of the manufacturer: Estonia
Name and address of the manufacturer: Laser Diagnostic Instruments AS, Valukoja street 11415
Tallinn, Estonia
Rating and principal characteristics: IP68, 12 V DC
Normative references: EN 60529
Test method: QMW 1303
Test scope: According to the order 7.1-3/17 at 08.05.2014
Trade mark (if any): -
Model/type reference: ROW-0-2300A
Additional information: Appendix 1
Product picture



Tested by: Harri Põldsalu
Expert

Inspecta
167

Inspecta Estonia OÜ
Teaduspargi 8, 12618 Tallinn, Estonia
Tel +372 659 9470 Faks +372 659 9479
estonia@inspecta.com
Laboratory address: Telliskivi 59, 10412 Tallinn

